

PAMPIERSTAD LANDFILL SITE

Site Photos taken in September 2015



Figure 1: Landfill is transacted by an access road from the centre. Picture show a view towards the south showing the access road to the site



Figure 2: Site is located nearby a residential development (in the background) View towards the north showing the access road from the site and the



Figure 3: The Pampierstad landfill viewed from the south



Figure 4: Agricultural farmlands (in the background) located to the north east of the site. Note excavation in the foreground
Picture taken from the south.



Figure 5: Close up view of the excavation in **Figure 4**



Figure 6: View towards the west showing an alternative view of other excavations on the site



Figure 7: The eastern portion of the landfill viewed from the west, note the extent of visual impact emanating from the dumping of waste



Figure 8: View of the south eastern part of the landfill. Note the extent of waste dumped on the site



Figure 9: View of the southern portion of the landfill, note the litter trap on existing trees



Figure 10: The south west portion of the Pampierstad landfill currently used for dumping of waste and reclamation



Figure 11: Picture shows the western portion of the Pampierstad landfill



Figure 12: The North west portion of the landfill is dominantly characterised by soil heaps



Figure 13: Windblown litter trapped on trees and grass surrounding the site, causing immense visual impacts



Figure 14: An example of the recycling initiatives taking place at the landfill